

Safariland Duty Gear Service Bulletin

PLEASE READ THIS IMPORTANT BULLETIN IN ITS ENTIRETY

August 15, 2021

RE: Safariland® 7TS™ GEN 2 ALS Light Bearing Holsters for Sig P320 / P320C and Surefire X300U

Safariland has recently become aware that <u>right-handed</u> 7TS[™] Duty Holsters (GEN 2) for the Sig P320 and P320C utilizing the ALS system when using the Surefire X300/X300U/X200 light attachment are not fully retaining the weapon to Safariland's specifications. Notably, this was discovered during internal testing and there has not been any reported issues in the field to date.

Starting at the end of March 2021, Safariland launched the 2nd generation 7TS holster in place of the previous generation for the Sig P320 / P320C weapons. Although similar in appearance, there is an obvious difference in physical appearance between Gen 1 and Gen 2 7TS holsters.

As depicted in the images below, the blue circle highlights the difference in "step-downs" between the Gen 1 and Gen 2 holsters, with the Gen 1 version having a slight slope in the light bearing section, while the Gen 2 version has two distinct "steps". The image on the next page also illustrates the difference as seen from the triggerguard side of the holster.



7TS Gen 1 Light Bearing Holster



7TS Gen 2 Light Bearing Holster



7TS Gen 1 Light Bearing Holster on left hand side, Gen 2 on right hand side

Importantly, the retention issue is ONLY present in the right-handed 7TS™ Gen 2 light-bearing holsters for P320/P320C and ONLY when using the Surefire X300/X300U/X200 light attachment. For avoidance of doubt, holsters using Streamlight TLR-1/TLR-1HL or similarly sized light attachments do not have this potential retention issue.

For reference, below is a listing of all effected models for Gen 2 models (as depicted above).

Model	Centercode
7360	4502/7502/4522
7365	4502/7502/4522
7362	4502/7502/4522
7390	4502/7502/4522
7395	4502/7502/4522
7392	4502/7502/4522
7354	4502/7502/4522
7355	4502/7502/4522
7384	4502/7502/4522
7385	4502/7502/4522
7304	4502/7502/4522
7305	4502/7502/4522
7378	4502/7502/4522
7377	4502/7502/4522
7376	4502/7502/4522
7379	4502/7502/4522

For confirmation, users are advised to check their holster and verify whether it is a Gen 2 version of the above-listed models.

The Safariland R&D team has completed a remedy for this issue and is preparing to release the corrective action. We currently anticipate that the solution will be available before the end of August and will entail the use of a new ALS lever which can be retrofit into the existing Gen 2 holster body.

Any Gen 2 holsters with a manufacturing date of 32/2021 shown on the back of the holster body (8/6/21) or later will already have the new ALS lever installed. Also, anything shipped out with the centercodes involved past 8/6/21 will have the new ALS lever installed.

IF you have an affected holster (i.e., 7TS™ Duty Holsters - GEN 2 for Sig P320 and P320C utilizing the ALS system), DO NOT use the Surefire X300/X300U/X200 light attachment and contact Safariland's Customer Service department for a resolution, which will include the new ALS lever.

We apologize for any inconvenience that this may cause but want to emphasize that officer safety is of utmost importance to us. If you have any further questions, please feel free to contact the Safariland Customer Service department, or you may also contact the Duty Gear team directly or your local sales representative.

Safariland, LLC
Attn: Customer Service Department
4700 E. Airport Dr.
Ontario, CA 91761
(800) 347-1200
(909) 923-7300